# **TRW Commercial Steering**

## **Diagnostic Tool**

Ver. 1.0.1.3

ct Device: Noregon Systems Inc.,	, DLA+ Adapter - DLA+ (100)	<b>•</b>	Rate: 250 kb 💌 🜔 Disconne
		Fault Codes	
Absolute Steering Position Valid:	TRUE	State	Code
Position Index Valid:	TRUE	Inactive	83
Absolute Steering Angle:	11.6 C-deg		) Dinan
System Mode:	NORMAL OPERATION		
Ground Speed:	Not Available		Reset Active Faults
Motor Torque:	-5.9 %	- Steering Controller In	nformation
Efforts Control:	683	Make: TRW (	Commercial Steering Systems
	1	Model: Colum	nDrive
Reset	t Straight Ahead	Software Identifie	cation: AP0006-G Feb 23 2016 NV0004
C DG TECHNOLOGIES	<b>A</b>	778	Duit

Valid software versions:

- AP0004-I
- AP0004-M
- AP0004-N
- AP0004-R
- AP0006-A

- AP0006-B
- AP0006-E
- AP0006-F
- AP0006-G
- AP9001-A

May 23, 2016

The TRW Torque Overlay Diagnostic Tool is intended to assist a service technician answer the following questions:

- 1. Is it wired correctly?
- 2. Is it operating correctly?
- 3. Is it installed correctly?
- 4. Is it calibrated correctly?
- 5. Are the right messages being sent from the vehicle?

In this document, partial screens will be shown to emphasize the information being discussed.

To use the tool, plug your J1939 hardware adapter into your computer and the vehicle diagnostic port.

Start the engine and set the wheels to straight ahead. If the steering wheel was moved more than 90 degrees, stop the engine, wait a few seconds, and restart it. When you turn the ignition on or off, you should hear a definite 'click' from the motor of the ColumnDrive.

Start the tool and select the appropriate hardware adapter from the list of those available on your Windows 7 computer. This program expects you to already have other J1939 diagnostic tools installed so it uses those RP1210A-compatable drivers.

Select Device:	Noregon Systems Inc., DLA+ Adapter - DLA+ (100)	
	Noregon Systems Inc., DLA+ Adapter - DLA+ (3)	1
	Noregon Systems Inc., DLA+ Adapter - DLA+ (4)	1
	Noregon Systems Inc., DLA+ Adapter - DLA+ (5)	
Absolute Ct	Noregon Systems Inc., DLA+ Adapter - DLA+ (6)	E
Absolute St	Dearborn Group DPA 5 Multi Application - DG DPA 5 Dual-CAN (MA) USB (1)	H
	Dearborn Group DPA 5 Multi Application - DG DPA 5 250K CAN (MA) CH1 USB (10)	4
Position Ind	Dearborn Group DPA 5 Multi Application - DG DPA 5 250K CAN (MA) CH2 USB (20)	

Select the correct communications rate then click 'Connect' to start communication. The tool must be reconnected every time the ignition is turned back on. Click 'Disconnect' if necessary then 'Connect' to restore a broken connection. Note that it is the same button.

	7	200	×
Rate: 250 kb 💌	Connect		
			Disconnect

## 1. Is it wired correctly?

To find out if the ColumnDrive is wired correctly, look at the lower right corner of the screen for the Steering Controller Information.



The software identification may be different than shown, depending on the specific settings required by your vehicle.

If this information does not appear, the ColumnDrive is not responding to this tool so the power, ignition, and J1939 wiring must be checked against the OEM wiring instructions. If those are all operating correctly, the column is apparently burned out and must be replaced.

(figures 1-4 here)

Pin No.	Signal	Wire	Item	Notes
	Name	Color		
1	V_IGN	Determine	Ignition switch status input	High requests ColumnDrive power-
		d by OEM		up.
				Low requests ColumnDrive power-
				down.
2, 3, 4,	N/A	N/A	Not used	
9, 10				
5,7	CAN_L_BUS		CAN low drive interface to	11939 CAN network connected
		Determine	vehicle	Duplicated CAN pip-out allows for
6, 8	CAN_H_BUS	d by OEM	CAN high drive interface to	CAN termination components
			vehicle	CAN termination components.

Pin	Signal	Typical Wire	Item	Notes
No.	Name	Color		
А	VBATT	Red	Positive battery supply to	
			ColumnDrive system	Suitable fuse required at battery (40A
В	Gnd	Black	Negative battery return to	when limited to 10 Nm)
			ColumnDrive system	



Pin No.	Signal Name
A	Battery Ground
В	Battery Power
С	CAN_H_BUS
D	CAN_L_BUS
E	Shield
F, G, H, J	N/A

## 2. Is it operating correctly?

At ignition on after reconnecting the battery, both <u>Absolute Steering Position Valid</u> and <u>Position Index</u> <u>Valid</u> will be false, the <u>Absolute Steering Angle</u> measurement will read zero, and the system should be in normal operation.

Absolute Steering Position Valid:	FALSE
Position Index Valid:	FALSE
Absolute Steering Angle:	0.0 C-deg
System Mode:	NORMAL OPERATION

Moving the steering wheel across straight ahead a few times should make both the <u>Absolute Steering</u> <u>Position Valid</u> and <u>Position Index Valid</u> measurements go true and the <u>Absolute Steering Angle</u> measurement go live. At this point in the diagnosis, that measurement has not yet been proven to be accurate.

Absolute Steering Position Valid:	TRUE
Position Index Valid:	TRUE
Absolute Steering Angle:	1.7 C-deg
System Mode:	NORMAL OPERATION

If the battery has not been disconnected since the last time the ColumnDrive was functioning, <u>Absolute</u> <u>Steering Position Valid</u> will be true and the <u>Absolute Steering Angle</u> measurement will be live when the ignition is turned on, with no movement of the steering wheel necessary.

Absolute Steering Position Valid:	TRUE
Position Index Valid:	FALSE
Absolute Steering Angle:	2.0 C-deg
System Mode:	NORMAL OPERATION

When the <u>Absolute Steering Angle</u> measurement becomes live, the ColumnDrive is operating normally.

Four conditions are known to exist that cause a ColumnDrive to appear inoperable.

Condition 1:

The ColumnDrive will be inoperable if it has detected an internal fault. Most internal faults will be inactivated by turning off the engine then restarting it but code 105 is one of the few that will not self-reset. Code 105 is set when there are too many other faults too often. Active faults will prevent normal operation but for diagnostic purposes, both active and inactive faults are displayed in the upper right part of the screen.

Select Device: Dearborn Group DPA	5 Multi Application - DG DPA 5 Dual-CAN (MA) US	B (1)	▼ Rate	: 250 kb 💌	Disconnect
		- Fault Code	S		
Absolute Steering Position Valid:	FALSE	State		Code	
		Inactive	)	145	
Position Index Valid:	FALSE	Inactive		83	
Absolute Steering Angle:	0.0 C-deg	Active		105	
System Mode:	SYSTEM FAILURE				
				Reset Active Fa	aults
Ground Speed:	0.0 kph			resser retive re	

If any internal fault is active, it may be deactivated by clicking 'Reset Active Faults'. When the reset process is completed, this prompt will appear.

i	Reset Fault Codes was successful! To complete the procedure: 1. Turn the ignition Off. 2. Wait 30 seconds. 3. Turn the ignition On.
	ОК

Click 'OK', disconnect the diagnostic program and turn off the ignition for 30 seconds. When you turn the ignition off, you will get the following message:



Click 'OK' to clear the message. After about 30 seconds, restart the engine and reconnect the program.



The active fault should now appear inactive and the system will operate normally.

Select Device: Dearborn Group DPA 5	5 Multi Application - DG DPA 5 Dual-CAN (MA) US	B (1)	•	Rate: 250 kb	• •	Disconnect
		Fault	Codes			
Absolute Steering Position Valid:	TRUE	Sta	te	Code		
		Ina	ctive	145		
Position Index Valid:	IRUE	Ina	ctive	83		
Absolute Steering Angle:	0.2 C-deg		cuve	105		
System Mode:	NORMAL OPERATION					
Ground Speed:	0.0 kph			Reset	Active Faults	

If the fault was temporary, it will remain cleared and normal operation will be restored but if it was a hard fault, it will reappear and the column must be replaced.

Most faults will clear themselves by turning the ignition off and then back on, which easily clears intermittent faults. If the ratio of faults to successful trips exceeds 3:18, fault 105 occurs, making the unit inoperable until this tool resets it. This tool does not repair whatever damage initially caused the fault, though. If faults continue to occur, the column must be replaced, regardless of the fault code, because there are no repairable parts inside it.

Condition 2:

The ColumnDrive will be inoperable as long as <u>Absolute Steering Position Valid</u> remains false. If <u>Position</u> <u>Index Valid</u> is true but <u>Absolute Steering Position Valid</u> remains false after the procedure on page 5, turn the steering wheel to the known straight ahead position and click 'Reset Straight Ahead'. <u>Position Index</u> <u>Valid</u> must be true and the vehicle must not be moving for this to work.

id: FALSE		
TRUE		
0.000 C-deg		
NORMAL OPERATION		
Reset Straight Ahead		

You will then be prompted to complete the reset process.



Normal operation should be restored. If you wish to check it with this tool, you must reconnect this diagnostic tool as has already been discussed.

Absolute Steering Position Valid:	TRUE
Position Index Valid:	TRUE
Absolute Steering Angle:	0.2 C-deg
System Mode:	NORMAL OPERATION

#### Condition 3:

The ColumnDrive will be inoperable if it is in some system mode other than normal operation. This happens during the normal power up and power down cycles but can also happen if it gets into Maintenance mode, usually caused by a diagnostic tool for some other component.

System Mode:	SOFT SHUTDOWN
System Mode:	POWER DOWN TESTS
System Mode:	POWER DOWN

All power up and power down conditions should be temporary, clearing at the end of the cycle.

System Mode:	MAINTENANCE

If the ColumnDrive gets into Maintenance,

The ColumnDrive will be inoperable as long as <u>Absolute Steering Position Valid</u> remains false. If <u>Absolute Steering Position Valid</u> remains false after the procedure on page 3, turn the steering wheel to the known straight ahead position and click 'Reset Straight Ahead'. <u>Position Index Valid</u> must be true and the vehicle must not be moving for this to work.

Absolute Steering Position Valid:	FALSE
Position Index Valid:	TRUE
Absolute Steering	0.000 C-deg
System	NORMAL OPERATION
Reset Straight Ahead	

You will then be prompted to complete the reset process.



Normal operation should be restored. If you wish to check it with this tool, you must reconnect this diagnostic tool as has already been discussed.

Absolute Steering Position Valid:	TRUE
Position Index Valid:	TRUE
Absolute Steering Angle:	0.2 C-deg
System Mode:	NORMAL OPERATION

Condition 4:

The ColumnDrive will appear to be inoperable if the hydraulic steering system is not providing sufficient torque to steer the vehicle.

|--|

If the vehicle is hard to steer but the motor torque is 100%, the problem is in the hydraulic system. Please use the normal hydraulic troubleshooting tools and techniques to solve this issue.

## 3. Is it installed correctly?

To determine if the ColumnDrive is installed correctly, start the engine, connect the tool, and watch the <u>Position Index Valid</u> value as you slowly turn the steering wheel back and forth within about 90 degrees of straight ahead. It will be false between the time the ignition is first turned on and the steering wheel is moved across the position index.



If the ColumnDrive is installed perfectly, the <u>Position Index Valid</u> value will turn true within 5 degrees of the actual straight ahead of the vehicle.

Position Index Valid:	TRUE
-----------------------	------

If the Absolute Steering Angle is reading somewhere close to 720 degrees in either direction when the steering wheel and road wheels are straight, the ColumnDrive has been started with the steering wheel two turns off-center. To test this, drive in a straight line at low speed or otherwise insure the road wheels and steering wheel are at straight ahead.

.939.ini	Absolute Steering Position	Valid: TRUE	
	Position Index Valid:	TRUE	
44	Absolute Steering Angle:	-719.7 C-deg	
939.db	System Mode:	NORMAL OPERATION	
	Ground Speed:	2.8 kph	
	Motor Torque:	13.1 %	
Setting niliar wit	Efforts Control:	497	
		Reset Straight Ahead	

- 1. Steer to each end of travel then back to the real straight ahead position, which should clear the erroneous center and force the Absolute Steering Position Valid to be false.
- 2. Follow the instructions for on page 8 above.

## 4. Is it calibrated correctly?

The only calibration required is for the Absolute Steering Angle measurement to be zero when the vehicle is at straight ahead. This is supposed to be an inevitable result of a correct installation, but this tool can check and rezero the measurement if necessary. To test it, drive the vehicle in a straight line, holding the steering wheel against a pull if necessary. The Absolute Steering Angle measurement should then read close to zero while driving straight. In this example, the system is off by 16.6 degrees CW. If the error is in the range of 5 to 30 degrees in either direction, stop the vehicle, hold the steering wheel at the position required to drive in a straight line, and click the Reset Straight Ahead control.



You will then be prompted to complete the process.



Calibrated operation should be restored. If you with to check it with this tool, you must reconnect the program as has already been discussed.

Absolute Steering Position Valid:	TRUE
Position Index Valid:	TRUE
Absolute Steering Angle:	0.2 C-deg
System Mode:	NORMAL OPERATION

## 4. Are the right messages being sent from the vehicle?

While not part of the ColumnDrive itself, tests for the required J1939 messages are provided in this tool to aid overall installation and diagnostics.

Ground speed:

The ColumnDrive requires J1939 message PGN 65265 for ground speed in order to provide speed-proportional handwheel efforts.

Correct readings:



When standing still, the Ground Speed measurement should read 0.0 kph.

Ground Speed:	

17.8 kph

When moving, the Ground Speed measurement should read the correct speed. Note that speed is measured in kph. If your speedometer is calibrated only in mph, the conversion is 1.6 kph = 1.0 mph.

Incorrect readings:

If the message is missing, the measurement will read Not Available. The handwheel efforts will be too heavy at low speed and too light at highway speed. The cure for this is to find out why the message is missing, using the diagnostic tools for the controller sending the message.

If multiple controllers are sending conflicting speed values, the measurement will flicker and cause erratic steering efforts. The cure for this is to resolve the conflict.

Driver-controllable high-speed efforts:

An optional ColumnDrive feature in some vehicles is for the driver to be able to make the system feel heavier or lighter at high speed at his discretion. This control has no effect while standing still. If the option is enabled, the Efforts Control measurement from J1939 message 65530 is displayed.

Correct readings:

Efforts Control:	920
Efforts Control:	101

The value should be within the range of 101 to 921.

#### Incorrect readings:

Values larger than 940 or smaller than 75 will cause the ColumnDrive to assume a failure of the external device and operate with a constant value of 512. This will make the driver's control ineffective. The cure for this condition is to repair the controller that is making the faulty message.



If the ColumnDrive expects the message but it is missing, the displayed measurement will read 'Not Available'. The cure for this is to discover why the controller that is supposed to generate this message is not doing its job using the diagnostic procedure for that device.

To leave the diagnostic program, click 'Disconnect' then 'Exit'.

		×	
۲	Disconnect		Exit